## WINLAND ELECTRONICS. INC.

# **WBTX-319**

## **Ouick Start Guide**



### SPECIFICATIONS

Transmitter:

- 2.71" L x .95" W x .56" D
- Tamper Switch: Included inside transmitter
- Probe Dimensions
- Cord length 6'
- Wireless signal range:
- Transmitter frequency:
- Unique code ID:
- RF Peak field strength:
- Operating Temperature:
- Relative Humidity:
- Storage Temperature:

- 7" W x 1 77" L x 38" D
- 600ft (200M), open air 319.5 MHz
- typical 36000 uV/m at 3m
- 32° to 122°F (0° to 50°C)
- 5 95% Non-Condensing
- -40° to 140°F (-40° to 60°C)
- Supervisory keep-alive interval: 70 minutes
- Code outputs: tamper, tamper restore, alarm, alarm restore, low battery
- Batteries: 2 CR2032. Approximate Battery Life: 5 years Replace Batteries: (2) Panasonic CRT2032, Energizer CR2032, or Duracell DL2032

Sump Pumps

STEP

THIS IS A OUICK GUIDE FOR EXPERIENCED INSTALLERS ONLY. FOR DETAILED INSTALLATION INSTRUCTION REFER TO DOCUMENTATION FOUND AT WWW.WINLAND.COM





Remove protective battery tab-pull





"Learn" WaterBug transmitter into the control panel





Enable "Programming Mode"

STEP

5

Open and close the case to "tamper" the device Customize name and settings as desired and touch "ADD"

ADD

STEP

<u>م</u>

Mount the

Transmitter above

the floor level (as

high as reasonably

possible) to prevent

water damage.

Attach probe to

floor or floor

baseboard with

adhesive strips

(included).

Tie off extra cord as

needed or desired.

#### FCC / IC Statement

This sequement has been tested and found to comply with the limits for a class # digital device, purvant to Part 15 of the FCC Multi-Ense limits are designed to provide reasonable protection against harmful interference in a reidential installation. This equipment generates, uses and can radiate radio frequency energy and, front installed and used in accordance with the instructions, may cause harmful interference to radio communications. Nowever, there is no guarantee that interference and in oth court in a paircialar installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that
- to which the receiver is connected.

Consult the dealer or an experienced radio/TV technician for help.

This device complies with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Cet appareil est conforme avec Industrie Canada exempts de licence standard RSS (s). Son fonctionnement est soumis aux deux conditions suivantes: (1) oct appareil ne doit pas provoquer d'interférences et (2) ext appareil doit accepter toute interférence, y compris celles pouvant causer un mauvais fonctionnement de l'appareil.

In accordance with FCC requirements of human exposure to radio frequency fields, the radiating element shall be installed such that a minimum separation distance of 20 cm is maintained from the general population.

FCC: 2ABBZ-WIN-WATER-319 IC: 11817A-WINWATER-319

This device complies with Part 15 of the FCC Bules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undexide operation. Changes or modifications not expensively approved by the party responsible for compliance could void the user's authority to operate the equipment.

This Class B digital apparatus complies with Canadian ICES-3B. Cet appareil numérique de la classe B est conforme à la norme NMB-003 du Canada.

```
MANUACTURES HEREF DOCLARES LA MARANTEL ANO DEPERSIONNELS, MANTINE DEPERS,
MANUACTURES DE LA MARANTEL ANO DEPERSIONNELS MARANTEL ANO DEPERSIONNELS MARANTEL DE LA MARANTEL DE MARANTEL DE LA MARANTEL DE LA MARANTEL DE MARANTEL D
```

#### NEED HELP? 800-635-4269 Ext 1 techsupport@winland.com

D-011-0173 Rev. A